

Windshield wiper System

Wiper motor



Replacement motor for early dual motor wiper systems

The Lucas motor for the dual motor wiper systems has long since been discontinued. Here is an aftermarket replacement for early Lucas wiper motors 500519P

Dual speed wiper motor RTC3867
(gear not included in motor drive housing)
Inquire about alternatives to other motors

The single speed synchronous wiper motor has been discontinued.



Washer jet (2 req) PRC2437



Wiper arms



Wiper arm, left PRC2620
Wiper arm, right PRC2621
ANCO universal replacement arm 20-10
Adaptor, Wiper arm to motor shaft STC987

Wipers & Washer

49

Windshield washer System

Note: The series II & IIA systems have been discontinued. The Series III system shown below can be fit to earlier Land Rovers.

Series III
Washer bottle PRC1080
Cap for bottle PRC1081
Fluid pick up 90608330



Washer motor, Series III STC575



Replacement windshield washer bottle kit

This kit includes a new bottle, new mounting bracket, new electric washer pump and can be fitted with a minimum amount of work. This is a cost effective way to set up a new washer system or replace a missing bottle and pump.

71740ALT



Wiper blades



PRC1330G



PRC1330P

Dual motor wiper system

use either PRC1330G or PRC1330P

Single motor systems

PRC1330G

HELP LINE: 661-257-8634
24 HOUR FAX: 661-257-9765



Check our web site for our **Specials**
www.britishpacific.com