


Lenses

Unique to US trucks, "NAS" spec lights and lenses can be very hard to find! Accurate restorations need the right parts, and BP is always looking to find them for you! Some of these have been out of production for years, and supplies are limited.



- | | |
|--|----------|
| 1 Ser. III '73-'74 'tall' tail light lens | 601716 |
| 2 Ser. IIA/III '63-'72 tail light lens | 37H6109L |
| 3 Ser. III back-up light lens
(Comes with new seal) | 37H7512 |
| 4 Ser. IIA/III '69-'74 red side marker assy | 57916 |
| 5 Ser. IIA/III rectangular reflector | 560889 |
| 5A Rubber gasket only | 608226 |
| 5B Chrome rim only | 608221 |

Interior Dome Light



Complete assembly

STC251

Front Parking Lamps



- | | |
|---------------------------------------|----------|
| Complete assembly, Ser II, IIA | 52240 |
| Lens, glass | 54583038 |
| Retaining ring, chrome | 572734 |
| Rubber body, long type | 262235 |
| Bulb holder, double filament | 576985 |

- | | |
|--------------------------------------|---------|
| Complete assembly, Ser III | RTC5012 |
| (Modern replacement, 3" across base) | |
| Lens, clear plastic | 589284 |
| Lens, amber plastic | 589285 |

Front Turn Signals



- | | |
|--|----------|
| Complete assembly, Ser II, IIA thru '68 | 52338 |
| Lens, clear glass | 37H6928L |
| Lens, amber glass | 54581651 |
| Lens, red glass | 576109 |
| Retaining ring, chrome | 572734 |
| Rubber body, short | 576105 |
| Bulb holder, single filament | 54584780 |

- | | |
|---|-----|
| Complete assembly, Ser IIA, III starting '69 | NLA |
| (recommend replacement with 532807 or RTC5013) | |

- | | |
|--------------------------------|--------|
| Lens, amber, for original lamp | 606424 |
|--------------------------------|--------|

- | | |
|---|--------|
| 3 inch replacement (rear turn signal light) | 532807 |
| Lens, amber plastic | 601720 |

- | | |
|------------------------------|---------|
| New style 3 inch replacement | RTC5013 |
| Lens, amber | 589285 |