

Front Fender Splash Guards

Series II, IIA up to '68 (sold as pair)	LR52 Out of Stock
Series IIA & III, '69 & newer Left side, LHD	MRC6083
Steering box cover	330460

Apron Panel (Fits behind front bumper)

IIA, III rounded type	395459
-----------------------	--------

Front Bumper, Galvanized

Bumper, aftermarket	564704
Bolt for mounting bumper	BH606321L
Nut	NY606041L
Washer	2219


Mud Flaps

Sold as pairs



Rear, 88, 109 regular	320590P	Out of Stock
Rear, 109 station wagon		NLA

Windshield



Glass (2 req)	MTC5318
Sealing rubber (2 req)	78159
Bottom seal (seals windshield frame to fire wall)	DWC500011
Top seal (seals windshield frame to hard top) NLA, use DWC500011 and cut off excess	



1965 Land Rover 109 Station Wagon and 1960 Land Rover Dormobile camped in Jaw Bone recreational area, California

HELP LINE: 661-257-8634
24 HOUR FAX: 661-257-9765



Check our web site for our **Specials**
www.britishpacific.com